



PLAN GIECIA Z KSZTAŁTAMI PRĘTÓW:

Nr. el.	Średnica	Ilość	Gatunek	Długość	Kg/m	Ciepota	Kształt gęsia
30	12	30	S500	1400	1,24	37,3	1400
31	12	22	S500	1900	1,89	37,1	1900
33	16	8	S500	1319	2,08	16,7	300
34	6	6	S500	1027	0,23	1,4	240
Suma:							92,4